

Joanne H. Senders 622 NW Westover Terrace Portland, OR 97210

February 26, 2019

Gearhart City Administrator City Hall 698 Pacific Way PO Box 2510 Gearhart, OR 97138

Dear Members of the Gearhart City Council:

I am a long-time property owner in Gearhart. I have a home at 101 N. Ocean across from the city park. My family and friends have used the park for years. I am writing this letter because I am concerned about the condition of the ground cover in the park.

For the last couple of years, the City has not properly maintained the park. It has allowed the grass to die off and be replaced by a ground cover with stickers. As a result, people with pets and children in sandals have avoided using the park because of the stickers in their feet. With summer approaching, I am asking that the City spread grass seed in the park and do something to reduce the weeds and stickers. The park is an integral part of Gearhart and enjoyed by so many. It should be properly maintained to encourage its use. The cost of repairing the ground cover should be relatively small. One option might be to send out a letter to property owners asking for contributions.

Sincerely,

en fraktigen in die gewiedere dat telependerig in den die deutste verbeitigen der den die deutsche in die deut Deutsche deutsche deutsche fraktigen fraktigen fraktigen deutsche deutsche deutsche deutsche deutsche deutsch

Joanne H. Senders Sewders

RDS:dms

COUNTY PUBLIC HEALTH & GEARHART CROSSING MEETING

Friday, February 22nd 2019

To open the meeting, each party went round the table/room:

Chad Sweet – Gearhart City Administrator; Kerry Smith (in Mayor Brown's absence) – City Councilor; Reita Fackerell – City Councilor; Mike McNickle – Clatsop County Public Health; Traci Williams – The Sweet Shop owner, Gearhart resident, potential buyer of Gearhart Crossing; Terry & Molly Lowenberg – current owners of Gearhart Crossing; Jessica Joye – State DEQ; Mark McFadden – Gearhart Public Works Director; Krysti Ficker – Gearhart Executive Administration; Stuart Emmons – Architect (came with Miss Williams); Bob Morey – Resident (came with Miss Williams)

Chad informed all present the City wished to record the meeting as record. No one objected. He questioned Traci's representation; the meeting was not solicited as a public meeting. Traci stated they were her "advisors". Terry stated concerns but opted to move forward with the meeting.

Traci began with ascertaining the meeting's genesis as simple due diligence to present her investor with a business plan and make an offer to buy the building. She said she hit some road blocks, asked questions, and needed further explanation.

Before continuing, Councilor Smith requested to read a statement from the Mayor. No one objected. It apologized for his absence, recognized Kerry as moderator, and identified todays goals as: Making sure all parties involved get the info requested, understand the jurisdiction of the City, County, and State in these matters, and understand the proper processes to follow moving forward. He labeled the meeting as "an informational gathering" only.

Councilor Smith wished to make clear the City's intention for the meeting was NOT to in any way imply or suggest something illegal occurred; the intention is to ascertain agency jurisdictions and septic system operation processes – "who is responsible for what".

Traci stated her intention to make an offer to purchase the building resulted in requests for information. Councilor Smith asked what information she is lacking. Chad referenced the City-provided information packet on the table put together through the previous week. He advised it contained detailed responses to each of Traci's questions, and a copy of her email. Chad offered to go through them.

Before responding to Chad's offer, Traci began to explain the issue of trying to make a business plan

without accurate numbers (utilities from realtor, pumping from County). She said the County file included a letter claiming someone had video showing (the Crossing) draining into the City's stormwater system. She was concerned as a potential buyer and current residential neighbor. She hoped to get to the bottom of it today. Terry questioned Traci's motives, but agreed to continue.

Chad made the recommendation again to cover each item within Traci's February 19th email; granted:

- 1) RE: documentation of the Crossing property hooked to a storm drain and video proof Chad walked the property with our Public Works Director and found no evidence of cross-connection, and advised the City has no evidence a video exists. Mike confirmed requesting the video from the complainant. It was never produced. Further details (if they exist) of the complaint could be obtained from County Public Health. He noted if the complaint was taken via phone, the likely only written record would be the file's provided email, and no weight was given to the allegation after refusal to produce the video.
- 2) RE: water consumption data for the Crossing back to 2007 Chad referenced packet's enclosed report and explained how to read the meter readings.
- 3) RE: the transfer of Conditional-Use permits and Non-Conforming Uses Chad referenced the provided zone code docs, all tagged and highlighted; Yes, a Conditional-Use permit follows the land and continues as long as conditions are met. Non-Conforming Uses are irrelevant to the Crossing property.
- 4) RE: building permit approval for the Crossing's alley/easement addition Chad referenced the provided copies of the permit, design, and Jim Brien's approval.
- 5) RE: permits for the moving of the holding tank Chad advised this request needed to go to Mike at County Public Health as the City's building permit process has nothing to do with tank septic systems. However, the City did provide copies of what we had from a previous/similar request, which Mike advised is everything in the file any way.
- RE: written denial of the building permit for an addition to 567 Pacific Way (The Sweet Shop)
 Chad referenced the included copies of Traci's submitted plans by contractor Hazen and the denial due to rear-yard setbacks.
- 7) RE: records of Crossing holding tank complaints Chad advised multiple system searches only produced the two already referenced (and included) emails. He also recalled two verbal complaints received, both from Traci. Chad requested all present parties let us know if other complaints we were unable to produce exist.

Chad asked if anyone had immediate questions on any of the provided responses. No one did. He certified all information requested has been provided to Traci and requested if Traci had further questions after reviewing the packet to reach out via written request as record.

Bob asked if he could ask Terry a question. Terry didn't approve and Councilor Smith agreed because the meeting was to be closed vs. public. Traci felt a meeting shouldn't be needed to obtain public records. Councilor Smith maintained the need for meeting was for all parties to gain an understanding of processes, to identify the people in each jurisdiction for problems, and to demonstrate the City hasn't covered up any kind of tie-in to a drain system after Traci came to the City Council suggesting there was one in not releasing information; he explained if the City doesn't give information, there is jurisdictional reason. The request for questions from the audience was denied.

Traci questioned emailed reference to a dye test suggestion, a 3-month gap in pumping, and multiple pumping companies. As the appropriate jurisdiction, Mike stated everything he had was in the file except for 2018 records currently being prepared, and resented implication things were purposely missing. He cited frustration with being accused of not providing information that he had already explained at the time of Traci's initial information request wasn't available until the end of February. Mike wanted record availability clearly stated for the record as the issue vs. non-compliance of the request. He offered to contact the pumping companies regarding gaps and Traci appreciated the offer.

At this point, Traci made a request for the meeting to end.

Chad reminded everyone the City requested the meeting to ensure all on the same page, address town rumors, and verify Traci received all needed information. He reiterated applicable jurisdiction: Mike septic/holding tank; The City land and water use.

Before closing, Mike asserted the dye test was only a suggestion not a requirement, and Terry agreed to it. Chad advised dye testing wasn't needed after conducting a downspout test. He stated again the City is satisfied there is no evidence of cross-connection and is on record. He also refuted the claim of a patch in the asphalt due to a water line break having any tie to the storm drain system.

Councilor Smith asked if Traci or anyone else had further questions. No one did. Councilor Smith thanked everyone for their time and ended the meeting.



Form submission from: Gearhart Elk & Wildlife

City of Gearhart Oregon via City of Gearhart Oregon <info@ci.gearhart.or.us>

Wed, Feb 20, 2019 at 3:10 PM

Reply-To: City of Gearhart Oregon <info@cityofgearhart.com>

To: krysti@cityofgearhart.com

Submitted on Wednesday, February 20, 2019 - 3:10pm

Submitted by anonymous user: 172.16.64.19

Submitted values are:

First Name: Reed Last Name: Morrison

Email Address: Kickpanels@yahoo.com

Phone: 9712852222

Type of Wildlife Encountered: Elk Type of Experience: Neutral

Feedback/Please Describe Your Experience: Born and raised in Dellmoor Loop and Surfpines area, I understand Elk behavior and patterns. I am a licensed Bonded and Insured Pest Control Tech, I am available to help homeowners deal

with Elk that are intruding on their property through legal, non lethal control techniques.

Would you like us to forward your feedback to the ODFW (Oregon Department of Fish & Wildlife): Yes

The results of this submission may be viewed at:

https://www.cityofgearhart.com/node/1441/submission/7531



698 Pacific Way • P. O. Box 2510 • Gearhart, Oregon 97138 • (503) 738-5501

February 25, 2019

TO: HONORABLE MAYOR MATT BROWN & COUNCIL MEMBERS

FROM: CHIEF OF POLICE

SUBJECT: SPEEDING ISSUE; SUMMIT/RIDGE DR/5TH ST

Enclosed are copies of speed survey sheets for a 2-week period, February 11-24, 2019. Myself and my officers conducted stationary patrol at different locations and times in this area using radar. Listed below are factual stats:

TOTAL OFFICER HOURS: 44 HRS & 5 MINS

TOTAL NUMBER OF VEHICLES: 539

TOTAL CITATIONS: 1
TOTAL: WARNINGS: 0

The streets in this area are narrow and the right-a-way area is obstructed or uneven or other. This causes most citizens to walk in the paved travel lane. A vehicle traveling at 25mph that passes within 3-5 feet of pedestrians (alone, in a group, walking a dog, etc.) might make them feel unsafe/endangered. On Ridge Dr. an operator(myself) of a vehicle traveling at 25mph seems fast, as the roadway is very narrow, and the right-a-way is obstructed.

As I was working the survey (0825-0930, 5 vehicles recorded) in this area, a citizen informed me that I had just missed the rush time for vehicles. So, I choose an earlier time (0720-0825, 14 vehicles record) at this same location (a few of these vehicles were multiple recordings). The fastest speed recorded on that date and time was 23mph. I was told by another citizen (at a different location) that if I had been here an hour ago, I would have caught a fast speeder. I have been contacted in the past, that there is a citizen in this area, that steps in front of vehicles and screams at drivers to slow down. Even though the drivers weren't speeding (25mph or less). In general, some citizens have a poor perception of speed. A loud vehicle is perceived to be traveling fast.

The citizens that contacted me while I was working the survey, appreciated that we were there (one citizen was concerned we were stalking/surveillance him, I was told). I took the liberty to ask them a few questions: How fast do you think these speeders are going? General answer was 30-35mph, maybe a few faster. Did you read the letter you signed? None had. Do you agree that speed bumps (Unlawful to Install) should be installed? No one wanted speed bumps. They do believe that posted "Speed" signs might help slow-down some drivers. (Our 25mph residential areas are not "speed limits").

I lived in this area from 1983-1991 (on Ridge Dr.) back when Gearhart had a population of 450 citizens. There were no housing developments in the area except ours on Ridge Dr. and Summit (dead-ended north side of 5th). But even back then, citizens would travel Summit and Ridge Drive on Friday and Saturday nights heavily to go to the drive-in theater. (Hwy 101 at 5th St. was a 55mph zone during these years)

There is no Law Enforcement fix to the concerns raised by the citizens of Summit/Ridge Dr/ 5th St. We do patrol the area but as shown in the survey sheets, where is the perceived issue. These same perceived issues are reported throughout the city. Maybe the authors of the Citizen Letter know but I can't recall the last time a person, dog or cat was struck by a vehicle. Nor can I recall the last time an operator of a vehicle caused property damage (speeding or otherwise) in this area.

One solution might be to clear the right-a-way and install raised sidewalks. Moving pedestrians off the travel portion of the roadway and elevating them, would make some pedestrians feel safer. A good example would be Holladay St. between 1st and 12th Ave. in the City of Seaside. Average cost per 800 sq. ft of sidewalk is approx. \$3,100.00 (my guess is that very few of the property owners would want to be assessed a fee for sidewalks). On streets such as Cottage and Marion, where walking paths are located, some pedestrians still choose to walk in the roadway. Some of the city's sidewalks and walking paths are in such poor condition, walking in a traffic lane is maybe safer.

Jeffrey T. Bowman

Chief of Police

	SUMMIT				
DATE:	021119	LOCATION: 44	8 Ridge	OV 50	TIME: 0 80
	SPEED	DIRECTION		SPEED	DIRECTION
1	16	5	21		
2	20	5	22		
3	7	5	23		
4	14	5	24		
5	19	N	25		
6			26		
7			27		
8			28	AMAZ 600-00-00-00-00-00-00-00-00-00-00-00-00-	
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

NOTEPOSSIBLE MULTIPLE RECORDINGS BY SAME VEHICLE(S) DURING ANY GIVEN SINGLE SURVEY PERIOD

	SUMMIT/I	RIDGE/5TH SP	EED S	URVEY	
DATE:	D21119	LOCATION: 5th	#Rida	e Drieb	TIME: 1125-
	SPEED	DIRECTION		SPEED	DIRECTION
1	25	W	21		
2	23	٤	22		
3	28	ω	23		
4	21	W	24		
5	26	E	25		
6	27	E	26		
7	19	W	27		
8	22	W	28		
9	25	W	29		
10	23	W	30		
11	27	٤	31		
12	22	ی	32		
13	24	E	33		
14	25	W	34		
15	20	e	35		
16	21	W	36		
17	21	\mathcal{W}	37		
18	70	2	38		
19			39		
20			40		

-1230

	SUMMIT	T/RIDGE/5TH SF	PEED SI	URVEY	
DATE	: <u>CAN19</u>	LOCATION:	11@ R100-6	FALL EB	TIME: 1720-18
	SPEED	DIRECTION		SPEED	DIRECTION
1	73	Eß	21		
2	99	WB	22		
3	15	WB	23		
4	72	WB	24		
5	17	WR	25		
6	29	WB	26		
7	19	EB	27		
8	わ	ws	28		
9	77	WS	29		
10	26	ER	30		
11	17	EB	31		
12	20	WB	32		
13	78	hr	33		
14	25	WB	34		
15	19	WB	35		
16	72	EL	36		
17	3)	WB	37		
18	77	WS	38		
19			39		
20			40		

	SUMMIT				
DATE:	021219	LOCATION:5	\$101	wB_	TIME: 0645
	SPEED	DIRECTION		SPEED	DIRECTION
1	21	WB	21		
2	24	WB	22		
3	26	EB	23		
4	27	WB	24		
5	27	eB	25		
6	25	EB	26		
7	20	EB	27		
8		WB	28		
9	22	WB	29		
10	21	WB	30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

			SUMMIT/	RIDGE/5TH SI		ED S	URVEY	
	DATI	E :	021219	LOCATION: 5	th A	Rid	ge Dr EB	TIME: 1125
1131			SPEED	DIRECTION			SPEED	DIRECTION
ite	<u>d</u> 1		36	WB		21		
	2		21	WB		22		
	3		20	WB		23		
	4		22	EB		24		
	5		21	EB		25		
	6		25	WB		26		
	7		33	WB		27		
	8		26	EB		28		
	9		23	EB		29		
	10		27	EB		30		
	11		31	WB		31		
	12		21	WB		32		
	13		19	MR		33		
	14		26	EB		34		
	15		26	EB		35		
	16		28	WB		36		
	17		26	EB		37		
	18		20	WB		38		
	19		23	CAW		39		
	20		24	60	desertation of the state of the	40		

	SUMMIT/	RIDGE/5TH SP	PEED SU	RVEY	***************************************
DATE:	021219	LOCATION:	BIKSOM	mit WB	TIME: \$\\phi 825 -
	SPEED	DIRECTION		SPEED	DIRECTION
1	22	NB	21		
2	26	58	22		
3	20	SB	23		
4	19	NB	24		
5	24	SB	25		
6			26		
7			27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SF				
DATE:	021219	LOCATION: 100	BIKSU	minit WE	TIME: 1615-	175
	SPEED	DIRECTION		SPEED	DIRECTION	-
1	25	5B	21			
2	21	NB	22			
3	24	3B	23			-
4	27	NB	24			
5	20	NB	25			
6	16	NB	26			
7	21	SB	27			
8	22	NB	28			
9	18	5B	29			
10	21	NB	30			
11	17	58	31			
12	16	NB	32			
13	17	NB	33			
14			34			
15			35			
16			36			
17			37			
18			38			
19			39			
20			40			

	SUMMIT/	RIDGE/5TH SP	EED SU	JRVEY	
DATE:	021319	LOCATION: 5	A Ride	je EB	TIME:0630-
	SPEED	DIRECTION		SPEED	DIRECTION
1	33	EB	21		
2	21	EB	22		
3	27	EB	23		
4	23	WB	24		
5	26	EB	25		
6	20	EB	26		
7			27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH S			
DATE:	021319	LOCATION: 40	OBIKRICA	elksb	TIME: 1/25-
	SPEED	DIRECTION		SPEED	DIRECTION
1	15	NB	21		
2	16	SB	22		
3		5B	23		
4	20	NB	24		
5	23	SB	25		
6	15	SB	26		
7	21	NB	27		
8	·		28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	/RIDGE/5TH SP	PEED SU	JRVEY	
DATE:	021319	LOCATION: 57	« Kony	5502 E/V	TIME: /871-19
	SPEED	DIRECTION		SPEED	DIRECTION
1	23	LV/2	21		
2	20	C~ /3	22		
3	26	w/3	23		
4	20	$\epsilon/\bar{\nu}$	24		
5	18	4/2	25		
6	20	w/2	26		
7	17	UB	27		
8	21	E/B	28		
9	19	EB	29		
10	34	w/z	30		
11	26	E/B	31		
12	3(wjz	32		
13	23	W/Z	33		
14			34		
15	·		35		
16			37		
17 18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SF	PEED SU	JRVEY	
DATE:	P1412	LOCATION: 100	BIK Su	munit NB	TIME: \$\\dig \8\id \cdot \\
	SPEED	DIRECTION		SPEED	DIRECTION
1	21	NB	21		
2	20	NB	22		
3	20	NB	23		
4	19	NB	24		
5		SB	25		
6	18	NB	26		
7	21	NB	27		
8	23	NB	28		
9	15	NB	29		
10	20	5B	30		
11	15	NB	31		
12	17	SB	32		
13	19	5B	33		
14	16	SB	34		
15	18	NB	35		
16			36		
17			37		
18			38		
19		,	39		
20			40		

7	SUMMIT	MIT/RIDGE/5TH SPEED SURV			
DATE	121419	LOCATION: 5-m	mit /R	also N/I	TIME: 1826-1
	SPEED	DIRECTION		SPEED	DIRECTION
1	24	5/2	21		
2	16	NA	22		
3	16	NA	23		
4	17	N/Z	24		
5	23	5/2	25		
6	18.	5/3	26		
7			27		
8	,		28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SP	EED SU	JRVEY	
DATE:	021519	LOCATION: 100	BIKS	oumnite	UBTIME: 0720
	SPEED	DIRECTION		SPEED	DIRECTION
1	23	56	21		
2	73	NB	22		
3	18	5B	23		
4	19	SB	24		
5	22	5B	25		
6	23	SB	26		
7	23	5B	27		
8	15	5B	28		
9	23	NB	29		
10	22	NB	30		
11	18	NB	31		
12	19	NB	32		
13	21	5B	33		
14	22	NB	34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

-0825 (Reported As Rush Hour time frame)

	SUMMIT/	SUMMIT/RIDGE/5TH SPEED SURVEY					
DATE:	28519	LOCATION:5	d	-10	1	WB	TIME: <u>0905</u> -
	SPEED	DIRECTION				SPEED	DIRECTION
1	31	EB		21		19	EB
2	22	WB		22		30	EB
3	27	EB		23		22	EB
4	18	WB		24		20	WB
5	19	$\mathcal{E}\mathcal{B}$		25		22	EB
6	21	WB		26			
7	24	WB		27			
8	16	EB		28			
9	23	WB		29			
10	25	WG		30			
11	23	WB		31			
12	24	EB		32			
13	19	EB		33			
14	24	εβ		34			
15	21	WB		35			
16	24	EB		36			
17	19	EB		37			
18	20	EB		38			
19	27	23		39			
20	21	EB		40			

	SUMMIT/	RIDGE/5TH SF	PEED S	SU	RVEY	
DATE:	021519	LOCATION: 5	# & Bi	dq	e EB	TIME: 1145 -
	SPEED	DIRECTION			SPEED	DIRECTION
1	24	EB	21		23	EB
2	18	EB	22		19	EB
3	25	WB	23		28	WB
4	27	EB	24		20	WB
5	26	WB	25		25	EB
6	20	WB	26		22	EB
7	21	WB	27		21	EB
8	26	WB	28		29	EB
9	18	EB	29			
10	21	EB	30			
11	25	EB	31			
12	23	WB	32			
13	23	WB	33			
14	24	WB	34			
15	20	EB	35			
16	23	EB	36			
17	22	WB	37			
18	27	WB	38			
19	24	WB	39			
20	33	EB	40			

	SUMMIT/				
DATE:	B1519	LOCATION:	081155	ommit n	URTIME: 1435
	SPEED	DIRECTION		SPEED	DIRECTION
1	17	NB	21		
2	29	NB.	22		
3	30	5B	23		
4	19	SB	24		
5	24	SB	25		
6	20	NB	26		
7	27	SB	27		
8	23	NB	28		
9	18	SB	29		
10	20	SB	30		
11	20	SB	31		
12	21	NB	32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

20IAIIAII I /						
122/5/9	LOCATION: 32	> 13/1	Riche Sp	TIME: 2024		
SPEED	DIRECTION		SPEED	DIRECTION		
17	NB	21				
; 7	N/3	22				
15	5/5	23				
16	5/2	24				
	/	25				
		26				
		27				
		28	3			
		29		```		
		30				
		31				
		32				
		33				
		34				
		39				
	17 17 15 16	DESTANCE SPEED DIRECTION	SPEED DIRECTION			

	SUMMIT/	RIDGE/5TH SF				
DAT	E:021619	LOCATION: 5	1 4 1	OI WB	TIME: <u>0840</u> -	0950
	SPEED	DIRECTION		SPEED	DIRECTION	
1	23	WB	21	24	WB	
2	17	ZB.	22	22	WB	
3	24	WB	23	18	EB	
4	25	WB	24	21	EB	
5	25	EB	25	26	EB	
6	24	EB.	26	22	EB	
7	20	EΒ	27	27	WB	
8	26	EB	28	19	EB	
9	29	EB	29	29	EB	
10	23	WB	30	23	EB	
11	20	EB	31	21	EB	
12	26	EB	32	24	EB	
13	22	EB	33	23	EB	
14	23	WB	34	26	EB	
15	26	EB	35	24	EB	
16	26	EB	36	24	WB	
17	24	WB	37	22	WB	
18	25	WB	38	21	EB	
19	19	WB	39	19	WB	
20	20	EB	40			

		SUMMIT/	RIDGE/5TH SI	PEED SI	JRVEY	
	DATE	:021619	LOCATION: 400	BIKRI	ge SB	TIME: 1115-
		SPEED	DIRECTION		SPEED	DIRECTION
	1	21	5B	21		
	2	17	5B	22		
	3	16	SB	23		
5harov	4	23	NB	24		
	5	20	SB	25		
	6			26		
	7			27		
	8			28		
	9			29		
	10			30		
	11			31		
	12			32		
	13			33		
	14			34		
	15			35		
	16			36		
	17			37		
	18			38		
	19			39		
	20			40		

	SUMMIT/	SUMMIT/RIDGE/5TH SPEED SURVEY					
DATE:	021619	LOCATION: 100	BIK	Sumit NB	TIME: 1310-		
	SPEED	DIRECTION		SPEED	DIRECTION		
1	23	NB	21				
2	24	NB	22				
3	21	SB	23				
4	19	NB	24				
5	16	5B	25				
6	17	NB	26				
7	26	NB	27				
8	23	NB	28				
9	25	NB	29				
10	28	SB	30				
11	19	SB	31				
12	16	SB	32				
13	15	SB	33				
14	18	56	34				
15			35				
16			36				
17			37				
18			38				
19			39				
20			40				

	SUMMIT	/RIDGE/5TH SF	PEED SU	JRVEY	
DATE:	02/6/9	LOCATION: 5	mmit /	Prolon N/F	TIME: 1914-
	SPEED	DIRECTION		SPEED	DIRECTION
1	25	5/2	21		
2	22	5/3	22		
3	25		23		
4	20	S/P	24		
5			25		
6			26		
7			27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	T/RIDGE/5TH SF	PEED SU	URVEY	
DATE	:C21619	LOCATION: <u>≤7</u>	o e Kinc	Ł FOCE EX	TIME: 1740
	SPEED	DIRECTION		SPEED	DIRECTION
1	27	ER	21		
2	73	Eß	22		
3	30	Eß	23		
4	25	ES	24		
5	21	EVS	25		
6	20	EB	26		
7	93	EK	27		
8	23.	ES	28		
9	30	Ex	29		
10	9)	W.R	30		
11	31	EB	31		
12	25	NX	32		
13			33		
14			34		
15	2		35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	/RIDGE/5TH SF	JRVEY		
DATE:	021719	LOCATION: 50	r/Rel	e C/3	TIME: 124 - 15
	SPEED	DIRECTION		SPEED	DIRECTION
1	.21	4/2	21		
2	23	W/2	22		
3	23	€/3	23		
4	21	6/2	24		
5	25	WE	25		
6	20	wp	26		
7	23	CB	27		
8	25	wp	28		
9	25'	W/>	29		
10	21	EP	30		
11	21	E/B	31		
12	23	EB	32		
13	24	E/B W/B	33		
14	24	W/B	34		
15	21	C/B	35		
16	28	W/Z W/Z	36		
17	26	W/Z	37		
18			38		
19			39		
20			40		

	SUMMIT/	//RIDGE/5TH SPEED SURVEY		URVEY	
DATE:	021719	LOCATION:	DK RE	ks 18/2	TIME: 1419
	SPEED	DIRECTION		SPEED	DIRECTION
1	No Read	N/B	21		
2	No Road	NIZ	22		
3	. "	117	23		
4	20	NIB	24		
5			25		
6			26		
7			27		
8			28		
9			29		
10			30		
11			31		
12 13			32		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT				
DATE	:02/718	LOCATION: Sin	e RMFE	FOCE ER	TIME: 1747
	SPEED	DIRECTION		SPEED	DIRECTION
1	25	WA	21		
2	15	WB	22		
3	19	WK	23		
4	77	ER	24		
5	97	WB	25		
6	16	EK	26		
7	23	WB	27		
8	17	WK	28		
9	25	EB	29		
10	31	WB	30		
11	18	ES	31		
12	26	WS	32		
13	13	hk	33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SPEED SURVEY			
DATE	821819	LOCATION: 5	1 B (2)	bl wB	TIME: 0850-
	SPEED	DIRECTION		SPEED	DIRECTION
1	26	EB	21		
2	25	WB	22		
3	23	EB	23		
4	23	EB	24		
5	18	EB	25		
6	20	EB	26		
7	21	EB	27		
8	23	EB	28		
9	21	EB	29		
10	25	WB	30		
11	21	EB	31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/				
DATE:	Ø21819	LOCATION: 5	# &R	dye EB.	TIME: 1250
	SPEED	DIRECTION		SPEED	DIRECTION
1	15	WB	21	23	WB
2	24	WB	22	15	WB
3	23	EB	23		
4	25	EB	24		
5	19	EB	25		
6	23	EB	26		
7	16	WB	27		
8	24	EB	28		
9	19	EB	29		
10	31	ϵB	30		
11	21	EB	31		
12	18	WB	32		
13	21	WB	33		
14	20	20	34		
15	24	EB	35		
16	17	WB	36		
17	31	WB	37		
18	15	EB	38		
19	23	EB	39		
20	27	WB	40		

	SUMMIT/RIDGE/5TH SPEED SURVEY					
DATE:	<u> </u>	LOCATION: Sin (o Rv	<u>ሃሪ ኒ</u>	FOCETR	TIME: /652-
	SPEED	DIRECTION			SPEED	DIRECTION
1	73	EB	21			
2	24	WB	22			
3	25	EB	23			
4	25	EB	24			
5	25	ES	25			
6	95	WB	26			
7	21	ES	27			
8	18	EB	28		WAARAA	
9	73	EB	29			
10	73	WR	30			
11	71	N/S	31			
12	24	WB	32			
13	23	EB	33			
14	7.7	WB	34			
15			35			
16			36			
17			37			
18			38	and the second s		
19			39			
20			40			

	SUMMIT/				
DATE:	021919	LOCATION:	5th # R	129eEB	TIME: 0615
	SPEED	DIRECTION		SPEED	DIRECTION
		DIRECTION		SPEED	DIRECTION
1	28	WB	21		
2	19	EB	22		
3	15	WB	23		
4	22	EB	24		
5	25	εß	25		
6	18	EB	26		
7	23	EB	27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15	·		35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SP	EED SI		
DATE:	021919	LOCATION:	BIKSW	noit NB	TIME: 125
	SPEED	DIRECTION		SPEED	DIRECTION
1	17	NB	21		
2	20	NB	22		
3	21	SB	23		
4	19	SB	24		
5	19	NB	25		
6	25	5B	26		
7			27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT/	RIDGE/5TH SF	PEED SU	JRVEY		
DATE:	021919	LOCATION: 40	OBIKR	diesB	TIME: 1435	-1545
	SPEED	DIRECTION		SPEED	DIRECTION	
1	17	5B	21			
2	18	NB	22			
3	17	NB	23			
4	23	5B	24			
5	1.5	NB	25			
6			26			
7			27			
8			28			
9			29			
10			30			
11			31			
12			32			
13			33			
14			34			
15			35			
16			36			
17			37			
18			38			
19			39			
20			40			

nanog

	SUMMIT/	RIDGE/5TH SP	EED SU	JRVEY	
DATE:	022019	LOCATION: 100	BIKS	Durint NB	TIME: 0120 -
	SPEED	DIRECTION		SPEED	DIRECTION
1	18	SB	21		
2		58	22		
3	IT	5B	23		
4	19	5B	24		
5	21	5B	25		
6	15	5B	26		
7	22	5B	27		
8	20	58	28		
9	22	NB	29		
10	21	NB	30		
11	16	SB	31		
12	18	NB	32		
13	21	niB	33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

(Reported as Rush Hour time frame)

	SUMMIT/RIDGE/5TH SPEED SURVEY				
DATE:	02019	LOCATION:	\$ 4101	WB_	TIME: 130-
	SPEED	DIRECTION		SPEED	DIRECTION
1	17	EB	21		
2	25	WB	22		
3	22	EB	23		
4	21	EB	24		
5	22	WB	25		
6	25	EB	26		
7	11	EB	27		
8	18	WB	28		
9	25	EB	29		
10	27	EB	30		
11	18	EB	31		
12	19	WB	32		
13	17	WB	33		
14	20	EB	34		
15	24	EB	35		
16	16	EB	36		
17	15	EB	37		
18	16	EB	38		
19	18	EB	39		
20			40		

	SUMMIT/I	RIDGE/5TH SF	PEED SU	JRVEY	
DATE:	\$2619	LOCATION: 10	SBIKS	ammit 1038	TIME: 1335-
	SPEED	DIRECTION		SPEED	DIRECTION
1	18	NB	21		
2	20	NB	22		
3	19	NB	23		
4	16	58	24		
5	18	5B	25		
6	19	NB	26		
7	20	NB	27		
8	20	NB	28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	T/RIDGE/5TH SF	PEED SU	JRVEY	
DATE	:02201	S LOCATION: 57	h. R.Jz	c E/B	TIME: 2144
	SPEED	DIRECTION		SPEED	DIRECTION
1	27	€/3	21		
2		,	22		
3			23		
4		· · · · · · · · · · · · · · · · · · ·	24		
5			25		
6			26		
7		. ,	27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	RIDGE/5TH SF	PEED SU	JRVEY		
DATE	092119	LOCATION:	BIKRI	agesB	TIME: 0815 - 0	AL.
	SPEED	DIRECTION		SPEED	DIRECTION	
1	19	5B	21			
2	22	NB	22			
3	18	NB	23			
4			24			
5			25			
6			26			
7			27			
8	,		28			
9			29			
10			30			
11			31			
12			32			
13	,		33			
14			34			
15			35			
16			36			
17			37			
18			38			
19			39			
20			40			

0000	SUMMIT/	RIDGE/5TH SPE	ED S	URVEY		
DATE:	122119	LOCATION:54	Rida	EB	TIME: 1(25	120
	SPEED	DIRECTION		SPEED	DIRECTION	
1	15	EB.	21			
2	26	EB	22			
3	22	NB	23			
4	22	WB	24			
5	21	WB	25			
6	24	WB	26			
7	24	EB	27			
8	1:1	WB	28			
9	22	EB	29			
10	28	WB	30			
11	28	WB	31			
12	25	WB	32			
13	27	WB	33			
14	21	MB	34			
15	19	WB	35			
16	17	WB	36			
17	16	WB	37			
18	21	88	38			
19			39			
20			40			

	SUMMIT	/RIDGE/5TH SF	PEED S	URVEY	
DATE	022/19	LOCATION:	Rick	n E/3	TIME: 1828-
	SPEED	DIRECTION		SPEED	DIRECTION
1	21	e/13	21		
2	2.3	€/≥	22		
3	25	UB	23		
4	22	W/Z	24		
5	25	WA	25		
6	28	6/7	26		
7	22	WF	27		
8	25	C/13	28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT				
DATE:	077710	LOCATION: ST	DO NU	y FACE WB	TIME: 2016-6
	SPEED	DIRECTION		SPEED	DIRECTION
1	18	WB	21		
2	23	WB	22		
3	19	WB	23		
4	24	WB	24		
5	22	WB	25		
6	7.7	WB	26		
7	20	WB	27		
8	21.	WB	28		
9	18	WB	29		
10	13	WB	30		
11	17	WB	31		
12	19	EB	32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	/RIDGE/5TH SF	PEED S	URVEY	
DATE:	022319	LOCATION:	mt/R	che Up	- TIME: 1046-
	SPEED	DIRECTION		SPEED	DIRECTION
1	16	5/2	21		
2	16	1/3	22		
3	19	N/J	23		
4	23	5 p	24	·	
5	23	5/2	25		
6	20	5/4	26		
7	22	N/iZ	27		
8	20	NB	28		
9	24	5/3 N/3	29		
10	25	11/3	30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT	/RIDGE/5TH SF	PEED S	URVEY	
DATE	UZZ319	LOCATION: 54	/ Rala	= 6/0-	TIME: 1547
	SPEED	DIRECTION		SPEED	DIRECTION
1	15	6/3	21		
2	12	E/3	22		
3	25	ep	23		
4	23	6/2	24		
5	12	6/2	25		
6			26		
7			27		
8			28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT				
DATE:	07376	LOCATION: ST	ne Huy	FACE WAS	TIME: /800-
	SPEED	DIRECTION		SPEED	DIRECTION
1	27	Eß	21		
2	19	WB	22		
3	43	WB	23		
4	13	EB	24		
5	18	EB	25		
6	17	WB	26		
7	20	WB	27		
8	22	EB	28		
9			29		
10			30		
11			31		
12			32		
13			33		
14			34		
15	·		35		
16			36		
17			37		
18			38		
19			39		
20			40		

	SUMMIT				
DATE:	022419	LOCATION: Sī	ACRI	OLE FACE ER	TIME: /800 - /8
	SPEED	DIRECTION		SPEED	DIRECTION
1	19	WB	21		
2	32	WB	22		
3	16	(E)B	23		
4	47	EB	24		
5	32	WB	25		
6	73	EB	26		
7	Lo	WB	27		
8	27	WB	28		
9	15	WB	29		
10	17	WB	30		
11			31		
12			32		
13			33		
14			34		
15			35		
16			36		
17			37		
18			38		
19			39		
20			40		

From: The City of Gearhart Residents of Summit Avenue and Ridge Drive

To: Gearhart City Council
698 Pacific Way
P.O. Box 2510
Gearhart, Ore. 97138

SUBJECT: Vehicular Residential Speeding on Summit Ave., 5th Street and Ridge Drive

Dear Gearhart City Council:

It is commonly known among local residents of Summit Avenue and Ridge Drive in the City of Gearhart that excessive vehicular speeding, particularly on Summit Ave. but also on Ridge Drive (to a lesser degree) as well as on 5th Street (east), which intersects Ridge Drive and Summit Ave., is an ongoing neighborhood concern that needs attention from the City's Leadership. This neighborhood vehicular speeding issue has been previously raised to City Leadership, but minimal consistent attention has been given to addressing it.

As a neighborhood, Summit Ave., Ridge Drive, and 5th Street (east) generally serve as local traffic conduits for various resident commuters who use these streets to access Pacific Way, Downtown Gearhart, and Highway 101. These residential Gearhart streets have served local neighborhood commuting needs for years, and no one disputes their value as useful traffic conduits for this purpose.

However, while these residential streets serve this neighborhood purpose, they also often serve as backchannel thoroughfares for various non-neighborhood and non-local commuters who choose to use them to conveniently access Pacific Way, Downtown Gearhart, as well as Highway 101, rather than travel to the main Gearhart intersection at Highway 101 and Pacific Way. Additionally, with new housing developments now situated just east of both Summit Ave. and Ridge Drive, it has also inevitably increased residential neighborhood traffic.

As a result, vehicular speeding on these residential streets to access Pacific Way, Downtown Gearhart, and Highway 101 has become a concern for the residents of this long-time Gearhart neighborhood.

The Summit Ave. and Ridge Drive neighborhood has long been largely comprised of year-round, local Gearhart residents. During most daytime hours it is common to encounter residents walking their dogs, or with children, or taking a private leisurely stroll around the "block." In addition, during busy seasonal weekends there are often vacationers with children, along with their pets, who can also be encountered walking, riding bikes, and otherwise enjoying these quiet neighborhood streets.

Finally, there are also neighborhood domestic family cats as well as other local wildlife that can be encountered when traveling these streets. Ongoing vehicular speeding by various commuters presents a potential danger and a nuisance to all who live along and enjoy these residential Gearhart streets.

This vehicular speeding issue on Summit Ave., 5th Street (east), and Ridge Drive needs to be addressed. The neighborhood resident signatories of this letter are requesting City Leadership take action on this residential speeding problem in an effort to help maintain and re-establish the neighborhood's long-time safety, quality and general serenity.

In that effort, three solutions to this residential vehicular speeding problem seem most evident:

- 1) Noticeably increase periodic law enforcement patrols, presence, and if necessary, enforce speeding penalties on these residential streets, particularly during high traffic periods in the early morning, lunch hour and early evenings.
- 2) Installation of maximum residential speed limit signs at both the Pacific Way and Summit Ave. intersection, and at the Summit Ave. and 5th Street (east) intersection.
- 3) Installation of local speed bumps on Summit Ave., Ridge Drive, and on 5th Street (east).

It is time for the City of Gearhart Leadership to take noticeable action on this issue. As has been emphasized in this request letter, the Summit Avenue and Ridge Drive neighborhood is a long-time Gearhart neighborhood that for years has been largely comprised of year-round, local residents. Residents have observed changes to the neighborhood over the years from city growth, and though still generally an enjoyable, peaceful neighborhood, the ongoing vehicular residential speeding problem stands out as a top neighborhood quality of life concern.

As signatories below, we are requesting the City of Gearhart address this neighborhood concern.

Sincerely,

The City of Gearhart Summit Avenue and Ridge Drive Neighborhood

Signed:

Name	Address		Signature	Date
KATHYWIBLY	448 Ridge	OR GEARMAN	KINIBUX	1-20-2019
Rather Kero	298 Ru	A	short Pure	160 1-20-20
	298 R.dge 1	3	Chall kn	1-20-2019
Frank J Flan		A 1	22-1	1-20-2019
Shiplev M. Jo	Shason 146		hyley m king	m 1-20-19
THOMAS CA	20 14	9 RTOGEN	Wigner C	Da 1-279
	1)		(

Name	Address	Signature	Date
MARIE	DLIVER 259 RIDGE T	on Marie Olive	1-20-19
• • •	a CATANOS 315 RIDG		1 FO-19
	Somethor 415 Ridge T		1.209
Marian	rne Palmbug 499 Ride	ge Dr. Mariane Par	Party 1-20-19
J. D. John	//	fre Genthart	1-20-19
111	657 SUMMIT	As MATT GORGE	1-20-19
Francis 1	a Pates of 787 Sun		
<i>f</i> .	Harris 949 Suma	nithu. Cherry Ha	rris (-20-1
7	Kloepfer 506 Ridg	ge Dr. Sham Ki	1/20/1
			.' 5 \$' +
and the second s		,	anangan ayangan gabar magan dagan antar da Milanda di Manda di Milanda di Manda di M
			· · · · · · · · · · · · · · · · · · ·
2			
3			
AND ADDRESS OF THE PARTY OF THE			
	•	***	4 1 2 2

This vehicular speeding issue on Summit Ave., 5th Street (east), and Ridge Drive needs to be addressed. The neighborhood resident signatories of this letter are requesting City Leadership take action on this residential speeding problem in an effort to help maintain and re-establish the neighborhood's long-time safety, quality and general serenity.

In that effort, three solutions to this residential vehicular speeding problem seem most evident:

- 1) Noticeably increase periodic law enforcement patrols, presence, and if necessary, enforce speeding penalties on these residential streets, particularly during high traffic periods in the early morning, lunch hour and early evenings.
- 2) Installation of maximum residential speed limit signs at both the Pacific Way and Summit Ave. intersection, and at the Summit Ave. and 5th Street (east) intersection.
- 3) Installation of local speed bumps on Summit Ave., Ridge Drive, and on 5th Street (east).

It is time for the City of Gearhart Leadership to take noticeable action on this issue. As has been emphasized in this request letter, the Summit Avenue and Ridge Drive neighborhood is a long-time Gearhart neighborhood that for years has been largely comprised of year-round, local residents. Residents have observed changes to the neighborhood over the years from city growth, and though still generally an enjoyable, peaceful neighborhood, the ongoing vehicular residential speeding problem stands out as a top neighborhood quality of life concern.

As signatories below, we are requesting the City of Gearhart address this neighborhood concern.

Sincerely,

The City of Gearhart Summit Avenue and Ridge Drive Neighborhood

Signed:

Name	A	Address		Signature	Date
Serany	Kust	276	Sommit	\mathcal{I}	1/13/19
,	Hordinark ,	230 Su	mnt). Cig	1/18/19
			4/16 Ridge	Rd	1/13/19
,	n Cool		427 Ridge		1/13/19
	ne Johnson		649 Sumn	_	1/13/19
	elym Johns		406 Samuel A	Inc	1-22-19
· · · · · · · · · · · · · · · · · · ·	A //				

This vehicular speeding issue on Summit Ave., 5th Street (east), and Ridge Drive needs to be addressed. The neighborhood resident signatories of this letter are requesting City Leadership take action on this residential speeding problem in an effort to help maintain and re-establish the neighborhood's long-time safety, quality and general serenity.

In that effort, three solutions to this residential vehicular speeding problem seem most evident:

- 1) Noticeably increase periodic law enforcement patrols, presence, and if necessary, enforce speeding penalties on these residential streets, particularly during high traffic periods in the early morning, lunch hour and early evenings.
- 2) Installation of maximum residential speed limit signs at both the Pacific Way and Summit Ave. intersection, and at the Summit Ave. and 5th Street (east) intersection.
- 3) Installation of local speed bumps on Summit Ave., Ridge Drive, and on 5th Street (east).

It is time for the City of Gearhart Leadership to take noticeable action on this issue. As has been emphasized in this request letter, the Summit Avenue and Ridge Drive neighborhood is a long-time Gearhart neighborhood that for years has been largely comprised of year-round, local residents. Residents have observed changes to the neighborhood over the years from city growth, and though still generally an enjoyable, peaceful neighborhood, the ongoing vehicular residential speeding problem stands out as a top neighborhood quality of life concern.

As signatories below, we are requesting the City of Gearhart address this neighborhood concern.

Sincerely,

The City of Gearhart Summit Avenue and Ridge Drive Neighborhood

Signed:

Name	Address	Signature	Date
Shawn Black	448 Sumait	Shan Rlyk	1-22-14
Joel Dierickx	298 Summit	Mykin	1/30/19
Do Frank	988 Sunnit		2-3-19
Jannine V	Vesterhaln 538 S	Summit J. West	Mu 2/3/19